Quantum
WOUND CARE. ANYWHERE.

INSTRUCTIONS FOR USE

NOTE: Please refer to the User's Manual for detailed instructions and review the Precautions and Contraindications before use.

1. Plug unit's power supply into a suitable power outlet. Plug power cable into right side of unit. For battery operation, please refer to the User's Manual.

2. Canisters are single-patient use only. Insert canister in holder by sliding up bottom right side of unit. Canister should "click" into place and lock. To remove canister, press canister release button, grasp canister at bottom and pull downwards. Canister may also be changed when the device is mounted in the I.V. Pole adapter. **NOTE: Canister release button may need to be depressed to permit canister insertion.**

3. Connect the distal end of the SpeedConnect Tube with the blue tapered connector to the patient port of the Canister. Gently twist and push connector on just enough to seal it. Make sure that the clamp on the SpeedConnect Tube is open. **NOTE: Please refer to the User's Manual for instructions on how to properly dress the wound.**

4. Press the ON ("I") button to start therapy. Adjust desired suction level by pressing the UP/DOWN arrow keys A green LED will begin flashing next to the therapy setting lighting steadily when pressure is achieved. The LED will flash if pressure cannot be maintained.

5. To lock therapy setting, press and hold the ON button for three seconds. The unit will beep three times indicating therapeutic setting is locked. Repeat process to unlock therapy setting.

6. To operate the unit in intermittent mode, press the CONTINUOUS/INTERMITTENT selection button. An amber LED will light indicating the device is in intermittent mode. Repeat process to return to continuous mode.

7. If device begins to alarm, please refer to troubleshooting table to identify and correct the alarm condition.

8. To turn device off, momentarily press the red OFF ("O") button. The LED display will flash "o-F-F" three times while the device is preparing to shut down.

NOTE: Each time the device is turned ON, the LED display will flash the number of days and hours of therapy remaining in the following format: d XX H YY.

Notice to Users:
As with any prescription medical device, failure to follow product instructions or adjusting settings and performing therapy applications without the express direction and/or supervision of your trained clinical caregiver may lead to improper product performance and the potential for serious or fatal injury.

For Questions and Information contact:
INNOVATIVE THERAPIES, INC.
GAITHERSBURG, MARYLAND
20877 U.S.A.
866-484-9678
www.ITIMEDICAL.com

ITI
Innovative Therapies Inc.
Outcomes Focused Wound Therapy

Quantum™ INSTRUCTIONS FOR USE

NOTE: Please refer to the User's Manual for detailed instructions and review the Precautions and Contraindications before use.

Alarm Type	Indication	Corrective Action
FLASHING "**0**" THERAPY TIME OUT	• Device is ready to be checked and serviced.	• Return device to representative for service.
FLASHING "**1**" LOW PRESSURE / DRESSING LEAK	• LED display flashes "1" accompanied by an intermittent single-tone audible beep. • Unit will continue to alarm until the low pressure/leak condition is corrected or the alarm is cleared.	• Pat around drape to check for leaks. If leak is found, patch with extra drape material. • Check all tubing connections between the therapy unit and dressing. • Check to ensure the canister is fully seated and locked. Check for cracks in the canister or lid separation.
FLASHING "**2**" CANISTER FULL	• LED display flashes "2" accompanied by an intermittent two-tone audible beep. • Unit will continue to alarm until the canister is replaced.	• Turn unit off by pressing the OFF button. • Remove canister and replace as necessary. • Press the ON button to resume therapy. • If conditions persist, the problem may be related to the device.
FLASHING "**3**" LOW BATTERY	• The LED display flashes "3" accompanied by an intermittent three-tone audible beep. • The unit will continue to alarm until connected to an A.C. power source. • When the charge falls below a critical level, the therapy will be discontinued.	• Utilizing an approved ITI A.C. Adapter, connect unit to an A.C. power source to provide operating power and to recharge the internal battery.

NOTE: Pressing the ON (MUTE) button after an alarm will silence the beeper for 5 minutes.

- **Defibrillation**: Remove the wound dressing if defibrillati0n is required in the area of dressing placement. Failure to remove the dressing may inhibit electrical current transmission and/or patient resuscitation.
- **Magnetic Resonance Imaging (MRI)**: The Quantum™ Wound Treatment Unit is not MRI-compatible. Do not take into the MRI area.
- **Hyperbaric Oxygen Therapy (HBO): NEVER allow a device—whether on or off—inside a hyperbaric chamber.** The device must be disconnected from the patient prior to HBO treatment. Refer to the Clinical Guidance for the Innovative Therapies Wound Treatment Systems for more information on use with HBO therapy.

ITI
Innovative Therapies Inc.
Outcomes Focused Wound Therapy